

2026 年度 安全管理優良工事等の公表について

多摩都市モノレール株式会社では、安全管理の取組みが特に優れ、事故の防止と安全輸送に多大な貢献のあった当社発注工事等の受注者に対し、表彰状を贈呈しました。

詳細は以下のとおりです。

1 対象案件

No.	件 名	受注者
1	防鳥ネット補修工事（緊急作業）	東京外装メンテナンス協同組合

2 表彰状贈呈

贈呈日 2026 年 6 月 1 日



東京外装メンテナンス協同組合 様


3 2026 年度選定対象期間

・ 2025 年 4 月 1 日から 2026 年 3 月 31 日までに完了した案件

以上

2026年度 安全管理優良工事等の概要及び選定理由

No.1

件名	防鳥ネット補修工事（緊急作業）		
受注者又は受託者名	東京外装メンテナンス協同組合 様		
現場代理人又は代理人名	現場代理人 百合野 毅 様		
主任技術者又は監理技術者	主任技術者 百合野 和磨 様		
契約日	2025年9月8日	完了日	2025年11月14日
工事内容	防鳥ネット補修工事 計5駅		
選定理由	<p>本工事は、駅舎ホーム上部鉄骨に設置された防鳥ネットの補修工事である。防鳥ネットは、上部鉄骨に営巣する鳥による被害を防止する目的で設置されているが、経年劣化によりネット補修が必要となった。当該箇所は施工時間が制限される上、仮設足場の設置が困難であり、特段の安全管理が求められる工事であった。表彰対象者は、上記状況を十分に把握した上で、仮設足場を必要としない「ロープアクセス工法」を提案・採用した。これにより、複数駅におけるネット補修を安全かつ迅速に実施し、万全の体制のもと無事故・無災害で工事を完遂した。その成果は、モノレールの安全輸送に大きく貢献するものであるとともに、他の模範となる優れたものである。よって、ここに安全管理優良工事として表彰する。</p>		
代表写真等	 <p>The collage consists of three photographs. The top-left photo shows a wide view of a station platform with a yellow and white striped ceiling. The top-right photo is a close-up of the ceiling structure with a red arrow pointing to a yellow mesh net labeled '防鳥ネット' (Bird Net). The bottom photo shows a worker in a green safety suit and harness suspended by ropes from the ceiling structure, with a red arrow pointing to the ropes labeled 'ロープアクセス工法' (Rope Access Method). Below the bottom photo is the label '作業状況' (Work Status).</p>		